

## Service Bulletin

**SB 14-1**  
**11-29-79**



SUBJECT: FUEL EVAPORATIVE SYSTEM  
VEHICLES: DINO 246 GT AND 246 GTS (U.S.A. VERSION)

**SERIAL NO:**

From Chassis No. 05686 to No. 05806

REISSUE OF TECHNICAL BULLETIN NO. 235, DATED 7/16/73

**SERVICE  
INFORMATION:**

When replacement of the control valve is required, make certain the new valve is installed properly (see illustration).

The proper position of the valve is

- White end of valve to liquid vapor separator
- Black end of valve to the activated carbon trap

**PARTS**

**INFORMATION:**

The control valve is a type CVX 2219, manufactured by Borg Warner corporation.

**RIGHT REAR WHEEL HOUSING**

