



Service Bulletin

SB 60-1
11-29-79

SUBJECT: CROMODORA WHEELS, PART NO. 111290
VEHICLES: 308GT4 AND GTB MODELS
SERIAL NO.: Before July, 1977 production

REISSUE OF TECHNICAL BULLETIN #317, DATED 10/24/77

CONDITION:

Possible interference between the front wheels and the upper front wishbones during full steering lock.

CAUSE: The thickness of the casting for Cromodora wheels Part No. 111290 has been increased.

CORRECTION:

When installing these wheels, make sure there is no interference between the wheel and upper wishbones.

If interference is experienced, remove sections of the wishbones as indicated in the illustration.

