



Service Bulletin

SB 80-7
11-29-79

SUBJECT: DISTRIBUTOR GUARDS
VEHICLES: DINO F106 U.S.A. VERSION

REISSUE OF TECHNICAL BULLETIN NO. 302, DATED 3/17/77

MODIFICATION:

To avoid an accumulation of moisture on the distributor cap:

- Drill 4 holes, approximately 4mm or 5mm (.1575" to .1969") in diameter, in the lower portion of the rubber guard (See illustration)

Vehicles presently in production have already been modified.

GUARD ON DISTRIBUTOR

LEFT HAND

RIGHT HAND

