

## Service Bulletin

**SB** 80-9  
11-29-79



SUBJECT: IGNITION DISTRIBUTOR  
VEHICLES: 308 GT4 U.S.A. VERSION

SERIAL NO.:

Starting from Engine No. 02599

REISSUE OF TECHNICAL BULLETIN NO. 321, DATED 12/6/77

MODIFICATION:

The connection between the distributor and camshaft has been changed. An aluminum plug has been installed on the distributor drive. See illustration.

SERVICE

INFORMATION:

To fit this aluminum plug to vehicles already in service, do the following:

- Remove Camshaft.
- Remove Distributor drive.
- Install plug to distributor drive.

NOTE: Before reinstalling distributor, grease splines.

- Reinstall components.

PARTS

INFORMATION:

The part number for the aluminum plug is 112547.

