

## Service Bulletin

**SB** 10-2  
7/3/80



SUBJECT: CAMSHAFTS

VEHICLES: 308 MODELS

REISSUE OF TECHNICAL INFORMATION NO. 360,  
DATED 2/14/80

### SERVICE INFORMATION:

The camshafts are manufactured with a hexagon located at the pulley side of the shaft.

Using the proper open end wrench on the hexagon, the camshafts can be held in position while removing or re-installing the drive pulleys.

