

Service Bulletin

SB 10-3
7-10-80



SUBJECT: ENGINE TIMING MARK

VEHICLES: ALL 308 MODELS

ENGINE NO: STARTING WITH ENGINE NO. F106USA 00801

SERVICE

INFORMATION:

To facilitate the checking of the engine timing, without removing the head covers, reference marks have been made on the external side of the camshafts.

To check the timing:

- Turn engine to top dead center.
- Install special tool AV 1198 (Part No. 95971198) on the camshaft close to the drive pulleys.
- Align the reference marks on the camshafts with the marks on special tool.

