



Service Bulletin

SB 10-7

8-5-82

SUBJECT: ENGINE TIMING GEARS
VEHICLES: All 308 Models Beginning With C.N. 38886
(Engine No. 1635)

SERVICE INFORMATION:

In order to improve quietness, the engine timing gears now have a modified tothing gear on the crankshaft, driven gears and oil pump gear.

<u>Old Part No.</u>	<u>Description</u>	<u>New Part No.</u>
103781	Crankshaft Gear	117655
112017	Drive Gear (for Camshaft)	117656
104574	Gear for Oil Pump	117659

NOTE: This Bulletin updates the Spare Parts Catalogue. The modified gears are not interchangeable with the gears previously used.