

Service Bulletin

SB 14-3
2-11-82




SUBJECT: FUEL HOSE CLAMPS
VEHICLES: ALL 308 MODELS



SERVICE

INFORMATION: When performing repairs to the fuel system, make sure hose clamps (A in diagram) are properly positioned, so that they do not interfere with the carburetor linkages (C).

CORRECT



INCORRECT



READ, INITIAL and PASS ON

SERVICE MANAGER	PARTS MANAGER	SERVICE WRITER	TECHNICAN