

Service Bulletin

SB 30-2
11-29-79



SUBJECT: SECOND GEAR SYNCHRONIZER PAWL
VEHICLES: 308 GT4, GTB, GTS (U.S.A. VERSION)

SERIAL NO.:

Starting with Gear Box No. 3130

REISSUE OF TECHNICAL BULLETIN NO. 323, DATED 2/15/78

MODIFICATION:

To improve shifting into second gear, the pawl for the second gear synchronizer has been changed.

IMPORTANT:

When overhauling a gearbox, replace the old type pawl with the new pawl.

PARTS

INFORMATION:

The part number for the new pawl is 113412.

