



Service Bulletin

SB 60-2
7-10-80

SUBJECT: FRONT WHEEL HUB

VEHICLES: 308 MODELS

SERIAL NO:	MODEL	STARTING WITH SERIAL NO.
	GT4	15350
	GTB/GTS	30065

SERVICE

INFORMATION: The front wheel hub components have been modified to improve protection against possible water infiltration.

PARTS

INFORMATION: The part numbers for the new components are listed below:

The old and new components are not interchangeable.

Ref. No.	Old Part No.	Description	New Part No.
13	104359	Sealing Ring	115968 (Double Ring)
10	104349	Wheel Hub	115966
7	113820	Right Stub Axle	115964
	104374		
7	113821	Left Stub Axle	115965
	104375		
14	104360	Spacer	115967
21	113818	Slinger Ring	Deleted

