

Service Bulletin

SB 60-3
8-28-80



SUBJECT: LOWER FRONT BALL JOINT

VEHICLES: 308 MODELS

SERIAL NO: MODEL STARTING SERIAL NO.

GT4 15092

GTB/GTS 29213

PARTS INFORMATION:

New lower ball joints have been installed on vehicles starting with the above mentioned serial numbers. The new ball joints will also be installed on future models.

The old and new ball joints are interchangeable.

<u>Old Part No.</u>	<u>Description</u>	<u>New Part No.</u>
---------------------	--------------------	---------------------

101442	Lower ball joint	114462
--------	------------------	--------