

## Service Bulletin

**SB 60-4**  
**1-22-81**



SUBJECT: FRONT HUB SEAL RINGS  
VEHICLES: ALL MODELS

SERVICE  
INFORMATION:

Before installing replacement seal rings on the front wheel hubs, the rings must be placed in an engine oil bath for at least 24 hours.  
Also, just before installation, the grooves in the seal rings must be packed with grease.

*READ, INITIAL and PASS ON*

SERVICE MANAGER	PARTS MANAGER	SERVICE WRITER	TECHNICAN			