

Service Bulletin

SB 96-1
11-29-79



SUBJECT: AIR CONVEYORS
VEHICLES: 308 GTB

REISSUE OF TECHNICAL BULLETIN NO. 299, DATED 3/1/77

SERVICE INFORMATION:

To avoid dirt entering the passenger's compartment through the air outlets

- Remove the two conveyors, (A in illustration) including gaskets, from the front of the electric fans.

Vehicles presently in production have already been modified.

