



## Service Bulletin

**SB** 96-2  
11-29-79

SUBJECT: HEATING SYSTEM  
VEHICLES: 308 GT4 AND GTB MODELS  
SERIAL NO: VEHICLES BUILT AFTER APRIL 1, 1977

REISSUE OF TECHNICAL BULLETIN NO. 306, DATED 9/1/77

### MODIFICATION:

The heating system was modified to equalize the temperature of , heat from the right and left passenger compartment air outlets. The following modification was performed.

- The water outlet hoses from the radiators (C and B in illustration) have been measured and then cut into two equal lengths of hose.

This allows the warm water from the radiator to travel an equal distance to the right and left heater boxes.

### SERVICE

### INFORMATION:

This modification can be performed on vehicles already in service.

