



Service Bulletin

SB 17-1

8-5-82

SUBJECT: WATER PUMP ASSEMBLY
VEHICLES: All 308 Models

NOTE: This cancels Service Bulletin 17-1 dated 2/11/82.
 Please discard previous bulletin.

PARTS INFORMATION:

A water pump with reinforced bearings is now available as a spare part for all 308 models.

The part numbers for the new water pump assembly and individual components are as follows: (See diagram below)

<u>Description</u>	<u>Part No.</u>	<u>Quantity</u>
Water Pump Assembly	116145	1
Main Shaft	103795	1
Bearing	116159	2
Spacer	116157	1
Snap Ring	11060076	1
Washer	116158	1
Pump Cover	116156	1
Sealing Ring	114410	1
Impeller	103806	1
Washer	10730301	1
Plate	100434	1
Nut	100436	1
Gasket	103952	1

