

SERVICE BULLETIN No

15-3

**PRODUCTION CHANGE**

DATE: 6/15/88


SUBJECT: CO / HC PROBE

VEHICLES: 328 USA / 3.2 MONDIAL USA

Starting from:	Model	328	Mondial			
	Area					
	Chassis no.	75609	75587			
	Engine no.	10516	10194			
	Gearbox no.					

**Description:**

A pipe is installed on the catalytic converter to check CO / HC in order to comply with the new Swiss regulations. The modification is extended on all ( 8 Cyl.) cars provided with catalytic converters.



**REPLACED PARTS**

**NEW PARTS**

ref. fig.	Part Number	Description	ref. fig.	Part Number	Description
-	110860	Plug	1	136747	Probe
-	10298460	Gasket	2	136251	Right bracket
			3	10418101	Clamp
			4	12644601	Washer
			5	116416	Nut
			6	16109642	Plug

Spare parts procedures:

Reference spare parts catalogue:

3.2 Mondial No. 473/87 Tav. 20 and 328 No. 462/87 Tav. 18

